

DID YOU KNOW?

PROTECT YOURSELF FROM HARMFUL UV RADIATION.

Every arc gives off ultraviolet light. Your helmet and FR clothing stop most of it; the skin they leave open still needs protection. A few simple habits cut the risk of burns and long-term skin damage.



THE DANGERS OF UV

- Welding arcs give off **UVA, UVB and UVC** rays.
- UV can burn exposed skin and inflame the eyes' cornea ("welder's flash").
- Repeated UV exposure raises the risk of **skin cancer** and early skin aging.
- Sparks and hot metal add thermal burns on top of UV.

WHY SUNSCREEN HELPS

- Sunscreen absorbs and reflects UVA and UVB before it reaches the skin.
- Zinc oxide, a mineral active, covers **both UVA and UVB** (about 290–400 nm).
- I.C. Industrial Sunscreen SPF 36 pairs non-nano zinc oxide with organic UV filters for **broad spectrum** protection.

TIPS ON THE JOB

- Apply broad spectrum sunscreen to all exposed skin **15 minutes before** the shift.
- Reapply after **80 minutes** of sweating and at least **every 2 hours**.
- Don't miss the neck, ears, face and wrists.
- Take breaks from UV exposure, and remind coworkers to use sunscreen and PPE.

ONE LAYER OF MANY

FR clothing and the right helmet shade come first. Sunscreen covers the gaps they leave; it is tested for UVA and UVB only and does not replace PPE.



I.C.® INDUSTRIAL SUNSCREEN SPF 36

A full broad-spectrum SPF 36 hybrid sunscreen, non-nano zinc oxide with organic UV filters, that goes on clear and holds through 80 minutes of sweat and water.

- Broad spectrum SPF 36, UVA and UVB
- 80-minute water resistant
- Clear, non-greasy and fragrance-free
- ASTM F2621 arc flash and D120 glove tested

Foils (box of 100 or 200), 50 mL airless, 2, 4 and 8 oz., 32 oz. pump and gallon.



SCAN

Welder sunscreen, sizes, TDS and SDS

ORDER DIRECT

(480) 443-9255
info@rrlotion.com

DISTRIBUTORS • GSA

Ask for the I.C. part numbers • GSA
MAS 47QSMS24D0078

Sun protection measures: Spending time in the sun increases your risk of skin cancer and early skin aging. To decrease this risk, regularly use a sunscreen with a Broad Spectrum SPF value of 15 or higher and other sun protection measures including limiting time in the sun, especially from 10 a.m. – 2 p.m., and wearing long-sleeved shirts, pants, hats, and sunglasses. Use only as directed; read the Drug Facts label.